



EMSL CANADA, INC.

10 Falconer Drive, Unit #3 Mississauga, ON L5N 3L8
Phone/Fax: 289-997-4602 / (289) 997-4607
http://www.emsl.com / mailto: torontolab@emsl.com

Order ID: 551204052
Customer ID: 55DOUG
Customer PO:
Project ID:

Attn: Client Contact
Canadian Customer Name
121 Haddon Ave
Westmont, NJ 08106

Phone:
Fax: (800) 555-1212
Collected: 08/31/2012
Received: 09/05/2012
Analyzed: 09/07/2012

Proj: 48 Tanager Drive, Guelph, ON

Surface Contamination ASSESSMENT Report™ Tape Samples Based on Direct Microscopic Analysis M041

Sample Information	Sample Location	Surface Contamination Rating (Referenced in IICRC S520)	Recommended Remedial Action (Referenced in IICRC S520)
Lab Sample #: 551204052-0013 Client Sample ID: TAPE LIFT #1	TAPE LIFT #1 - BASEMENT	Condition 1: Normal fungal ecology	<input checked="" type="checkbox"/> None Required
Lab Sample #: 551204052-0014 Client Sample ID: TAPE LIFT #2	TAPE LIFT #2 - BASEMENT	Condition 3: Actual fungal growth	<input type="checkbox"/> Remediate to a Condition 1 status
Lab Sample #: 551204052-0015 Client Sample ID: TAPE LIFT #3	TAPE LIFT #3 - BASEMENT	Condition 2: Contaminated with settled spores	<input type="checkbox"/> Remediate to a Condition 1 status
Lab Sample #: 551204052-0016 Client Sample ID: TAPE LIFT #4	TAPE LIFT #4 - BASEMENT	Condition 2: Contaminated with settled spores	<input type="checkbox"/> Remediate to a Condition 1 status
Lab Sample #: 551204052-0017 Client Sample ID: TAPE LIFT #5	TAPE LIFT #5 - BASEMENT	Condition 2: Contaminated with settled spores	<input type="checkbox"/> Remediate to a Condition 1 status
Lab Sample #: 551204052-0018 Client Sample ID: TAPE LIFT #6	TAPE LIFT #6 - BASEMENT	Condition 3: Actual fungal growth	<input type="checkbox"/> Remediate to a Condition 1 status
Lab Sample #: 551204052-0019 Client Sample ID: TAPE LIFT #7	TAPE LIFT #7 - BASEMENT	Condition 3: Actual fungal growth	<input type="checkbox"/> Remediate to a Condition 1 status
Lab Sample #: 551204052-0020 Client Sample ID: TAPE LIFT #8	TAPE LIFT #8 - BASEMENT	Condition 3: Actual fungal growth	<input type="checkbox"/> Remediate to a Condition 1 status

Definitions (from IICRC S520 Standard)

- Condition 1 (normal fungal ecology): an indoor environment that may have settled spores, fragments, or traces of actual growth.
- Condition 2 (settled spores): an indoor environment which is primarily contaminated with settled spores that were dispersed directly or indirectly from a Condition 3 area, and which may have traces of actual growth.
- Condition 3 (actual growth): an indoor environment contaminated with the presence of actual mold growth and associated spores. Actual growth includes growth that is active or dormant, visible or hidden.

Data provided in this report are intended to facilitate the assessment process performed by an Indoor Environmental Professional (IEP). The IEP is responsible for final data interpretation and remediation conclusions based on their assessment which may include information on the building history, an inspection, sampling, and laboratory data. Post-remediation verification testing recommended after any remediation.

A. Manager, Laboratory Manager
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation of the data contained in this report is the responsibility of the client. "*" denotes not detected. Samples received in good condition unless otherwise noted.
AIHA-LAP, LLC--EMLAP Lab 100194

Initial report from:

For Information on the fungi listed in this report please visit the Resources section at www.emsl.com