



# **EMSL Analytical, Inc.**

107 Haddon Avenue, Westmont, NJ. 08108 (856) 858-4800

**Attn.** Contact Person  
**Client:** Business Name  
Street Address  
City, State Zipcode

**EMSL Order:** 370000000  
**Received:** 01/01/09  
**Analysis Date:** 01/08/09  
**Report Date:** 01/08/09

**Project:** Water pipes

## **Detection of Nitrifying Bacteria in Water Samples with the N-BART™ System (EMSL Method: M127)**

<b>Lab Sample Number</b>	<b>Client Sample ID</b>	<b>Sample Location</b>	<b>Amount Analyzed</b>	<b>Nitrifying Bacteria (Present/Absent)</b>	<b>Potential Population Size (CFU/mL)</b>
0000-6	WT-06	Corroded Pipe	10mL	Present	10,000

EMSL maintains liability limited to cost of analysis. Interpretation of the data contained in this report is the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. The above test report relates only to the items tested. EMSL bears no responsibility for sample collection activities or analytical method limitations.

Dennis Kinney, Ph.D.  
**Laboratory Manager**  
or Approved EMSL Signatory